

# Contents

<b>Preface</b>	<b>xxiii</b>
<b>Scope</b>	<b>xxv</b>
Notes on the use of this publication	xxvi
<b>1 Layout of drawings</b>	<b>1</b>
1.1 General	1
1.2 Drawing sheets	1
1.3 Title block	2
1.4 Borders and frames	2
1.5 Drawing formats	2
1.6 Types of drawings	3
1.7 Marking	5
<b>2 Scales</b>	<b>7</b>
2.1 General	7
2.2 Recommended scales	7
2.3 Choice of scales	7
<b>3 Projection</b>	<b>9</b>
3.1 General	9
3.2 Projection symbols	9
3.3 Recommended proportions	10
3.4 Examples of first and third angle projection	10
<b>4 Lines and terminators</b>	<b>13</b>
4.1 General	13
4.2 Presentation	13
4.3 Line width	13
4.4 Types of line and their application	14
4.5 Coinciding lines	16

4.6	Leader lines and reference lines	17
4.7	Terminators and origin indication	19
<b>5</b>	<b>Lettering and numerals</b>	<b>21</b>
5.1	General	21
5.2	Style	21
5.3	Character height	21
5.4	Direction of lettering	21
5.5	Location of notes	22
5.6	Underlining	22
<b>6</b>	<b>Views</b>	<b>25</b>
6.1	General	25
6.2	Number of views	25
6.3	Partial views	25
6.4	Partial views of symmetrical parts	26
6.5	Interrupted views	27
6.6	Representation of repetitive features	28
<b>7</b>	<b>Sections and sectional views</b>	<b>31</b>
7.1	General	31
7.2	Arrangement	31
7.3	Cutting planes	31
7.4	Hatching	32
7.5	Types of sectional views and sections	34
7.6	Parts and features of parts not normally sectioned	40
<b>8</b>	<b>Symbols and abbreviations</b>	<b>43</b>
8.1	General	43
8.2	Welding symbols	43
<b>9</b>	<b>Item references</b>	<b>45</b>
9.1	General	45
9.2	Arrangement	46
9.3	Similar items used more than once	46
9.4	Associated items	46
9.5	Assembly instructions	46

<b>10 Representation of features</b>	<b>49</b>
10.1 General	49
10.2 Adjacent parts	49
10.3 Imaginary intersections	49
10.4 Simplified representation of intersections	50
10.5 Square ends of shafts	52
10.6 Surface pattern	53
10.7 Splines and serrations	53
10.8 Screw threads	54
<b>11 Representation of components</b>	<b>57</b>
11.1 General	57
11.2 Rolling bearings	57
11.3 Gears	58
11.4 Springs	61
<b>12 Dimensioning</b>	<b>65</b>
12.1 General	65
12.2 Types of dimension	65
12.3 Application	66
12.4 Elements and methods of dimensioning	68
12.5 Extension lines, dimension lines and leader lines	68
12.6 Terminations and origin indication	70
12.7 Indicating dimensional values on drawings	71
12.8 Arrangement and indication of dimensions	76
12.9 Chain dimensioning	76
12.10 Gaps between extension lines and features	76
<b>13 Dimensioning from a common feature</b>	<b>79</b>
13.1 General	79
13.2 Dimensioning by coordinates	81
13.3 Combined dimensioning	82
13.4 Chords, arcs, angles and radii	83
13.5 Equally spaced repeated features	84
13.6 Holes	86
13.7 Chamfers and countersinks	87
13.8 Other indications	88

13.9	Indication of levels	90
13.10	Levels on vertical views and sections	90
13.11	Levels on horizontal (plan) views and sections	91
13.12	Levels on site layout	92
13.13	Dimensioning of curved profiles	93
<b>14</b>	<b>Tolerancing</b>	<b>97</b>
14.1	General	97
14.2	Application of tolerances	97
14.3	Tolerancing of individual linear dimensions	97
14.4	Angular tolerances	98
14.5	Geometrical tolerances, datums and datum systems	99
14.6	Limits of size for the control of form	100
14.7	Limits of size with independency of size and form	101
14.8	Limits of size with mutual dependency of size and form	102
14.9	Envelope requirements	104
14.10	The maximum material principle	107
14.11	Least material requirement	138
14.12	Completeness of drawings	144
<b>15</b>	<b>Graphical symbols for the indication of surface texture</b>	<b>147</b>
15.1	General	147
15.2	The basic graphical symbol	147
15.3	Expanded graphical symbols	147
15.4	Mandatory positions for the indication of surface texture requirements	148
15.5	Surface texture parameters	150
15.6	Indication of special surface texture characteristics	151
15.7	Indications on drawings	153
<b>16</b>	<b>Diagrams</b>	<b>159</b>
16.1	General	159
16.2	Definitions	159
16.3	Principal types of diagrams	159
16.4	Symbols	160
16.5	Choice of symbol	160
16.6	Explanatory notes	160
16.7	Use of colour	160

<b>17 Microcopying and storage</b>	<b>163</b>
17.1 General	163
17.2 Drawing sheets	164
17.3 Density, thickness and spacing of lines	164
17.4 Areas	165
17.5 Markings	165
17.6 Lettering	166
17.7 Pencil drawings	166
17.8 Erasure	167
17.9 Storage	167
<b>Annex A (informative): Examples of mechanical engineering drawings</b>	<b>169</b>
<b>Annex B: Illustrative index to BS 8888</b>	<b>173</b>
<b>Annex C (informative): Approaches to 3D modelling</b>	<b>235</b>
<b>Annex D (informative): A model of Geometric Product Specification (GPS) and verification</b>	<b>237</b>
<b>Annex E (informative): Examples of the application of different types of line</b>	<b>247</b>
<b>Index</b>	<b>257</b>

## List of figures

---

Figure 1: Relationship of the 'A' sizes	1
Figure 2: Borders	3
Figure 3: Types of drawings	3
Figure 4: Method of indicating that the independency system of tolerancing has been used	5
Figure 5: Method of indicating that the dependency system of tolerancing has been used	5
Figure 6: Symbols indicating methods of projection	9
Figure 7: Recommended proportions for projection symbols	10
Figure 8: Examples of projections	10
Figure 9: Priority of coinciding lines	17
Figure 10: Examples of leader lines and reference lines	17
Figure 11: Dimensioning repeated to avoid long leader lines	18
Figure 12: The use of reference letters to avoid long and intersecting leader lines	18
Figure 13: Terminators	19
Figure 14: Origin indication (BS 8888 option)	19
Figure 15: Partial view projected from an inclined feature	25
Figure 16: Enlarged partial view	26
Figure 17: Symmetrical parts	27
Figure 18: Interrupted views	27
Figure 19: Representation of repetitive features	28

Figure 20: Positioning repetitive features relative to single features	29
Figure 21: Indication of a cutting plane	32
Figure 22: Hatching separated areas and adjacent parts	33
Figure 23: Hatching large areas	33
Figure 24: Section through thin material	34
Figure 25: Sectional view in one plane	34
Figure 26: Sectional view in two parallel planes where the change in direction of the cutting plane occurs on a centre-line	35
Figure 27: Sectional view in three parallel planes where the change in direction of the cutting plane does not occur on a centre-line	35
Figure 28: Sectional views in intersecting planes	36
Figure 29: Half-section view of a symmetrical part	37
Figure 30: Local or part sectional view	37
Figure 31: Revolved sections	37
Figure 32: Removed sections	38
Figure 33: Successive sections	39
Figure 34: Cutting plane passing longitudinally through fasteners	40
Figure 35: Item references	45
Figure 36: Adjacent parts	49
Figure 37: Imaginary intersection lines	50
Figure 38: Simplified representation of the intersection of two cylinders	50
Figure 39: Simplified representation of the intersection of two cylinders	51

Figure 40: Simplified representation of the intersection of a cylinder and a rectangular prism	51
Figure 41: Simplified representation of the intersection of two cylinders	51
Figure 42: Simplified representation of the intersection of a cylinder and a rectangular prism	51
Figure 43: Indication of flat features on a shaft	52
Figure 44: Indication of tapered flat features on a shaft	52
Figure 45: Examples of knurling	53
Figure 46: Splines	53
Figure 47: Serrations	54
Figure 48: Conventions for screw threads	55
Figure 49: Conventions for assembled screw threads	56
Figure 50: General representation of a rolling bearing	57
Figure 51: Conventional representation for gears	58
Figure 52: Examples of gears where only one or two teeth need to be shown	59
Figure 53: Conventions for gears in mesh	60
Figure 54: Chain wheels	61
Figure 55: Conventions for representing cylindrical helical springs	61
Figure 56: Functional and non-functional dimensions	66
Figure 57: Functional dimensioning	67
Figure 58: Indirect functional dimensioning	67
Figure 59: Extension lines and dimension lines	68



Figure 60: Extension lines and dimension lines	68
Figure 61: Dimension lines drawn obliquely, but parallel	69
Figure 62: Intersecting construction and extension lines	69
Figure 63: Unavoidable intersection of dimension and extension lines	69
Figure 64: Dimensioning a broken feature	69
Figure 65: Centre-line and/or outline of a part used in place of an extension line	70
Figure 66: Arrowhead termination within the limits of the dimension line	70
Figure 67: Arrowhead termination outside the intended limits of the dimension line	70
Figure 68: Radius dimensioning	71
Figure 69: Indicating dimensional values	71
Figure 70: Dimension values on oblique dimension lines	72
Figure 71: Angular dimensions orientation	72
Figure 72: Angular dimensions orientation	72
Figure 73: Dimensional value closer to its termination	73
Figure 74: Dimensional values above their dimension line, where limited space is available	73
Figure 75: Dimensional value above a horizontal extension of its dimension line	73
Figure 76: Values for out-of-scale dimensions	74
Figure 77: Diameter values	74
Figure 78: Radial values	75

Figure 79: Square values	75
Figure 80: Spherical radius values	75
Figure 81: Spherical diameter values	75
Figure 82: Chains of single dimensions	76
Figure 83: Parallel dimensioning	79
Figure 84: Superimposed running dimensions – values in line with the corresponding extension line	80
Figure 85: Superimposed running dimensions – values above their dimension line	80
Figure 86: Superimposed running dimensions in two different directions	80
Figure 87: Tabulated dimensional values	81
Figure 88: Coordinates for intersections in grids or block plans	81
Figure 89: Coordinates for arbitrary points of reference adjacent to each point	81
Figure 90: Coordinates for arbitrary points of reference in tabular form	82
Figure 91: Combining single dimensions and dimensioning from a common feature	82
Figure 92: Combining single dimensions and chain dimensions	82
Figure 93: Dimensioning of chords, arcs and angles	83
Figure 94: Indicating a radius where its value has been derived from other dimensions	84
Figure 95: Dimensioning of linear spacings	84

Figure 96: Dimensioning of linear spacings to avoid confusion	84
Figure 97: Dimensioning of angular spacings	85
Figure 98: The omission of angles of spacings to avoid confusion	85
Figure 99: Dimensioning circular spacings	85
Figure 100: Defining a quantity of elements of the same size: linear	86
Figure 101: Defining a quantity of elements of the same size: circular	86
Figure 102: Hole dimensioning	87
Figure 103: Chamfer dimensioning	87
Figure 104: 45° chamfers simplified	87
Figure 105: Dimensioning internal chamfers	87
Figure 106: Dimensioning countersinks	88
Figure 107: Dimensioning with reference letters	88
Figure 108: Dimension lines in partially drawn views and partial sections of symmetry	89
Figure 109: Dimensioning an assembly	89
Figure 110: Dimensioning a limited length of a special condition to an element of revolution	89
Figure 111: Clear indication of the extent of a special condition with no dimensioning	90
Figure 112: Indicating the predetermined base-zero level	90
Figure 113: Indicating the altitude of the base-zero level	90
Figure 114: Indicating subsequent levels on vertical views and sections	91

Figure 115: The numerical value of a level for a point	91
Figure 116: Indicating the level if the specific location point is defined by two intersecting lines	92
Figure 117: Location of a numerical value of an elevation or an outline	92
Figure 118: The dimensioning of a curved profile	93
Figure 119: Linear coordinates of a series of points through which a profile passes	94
Figure 120: Specifying dimensions in association with a follower	94
Figure 121: Specifying angular tolerances	98
Figure 122: Specifying geometric tolerances	99
Figure 123: Interpretations using the principle of independency for a cylindrical component for which a tolerance of size only is specified	102
Figure 124: Interpretation of limits of size with dependency of size and form	103
Figure 125: Indication of envelope requirement	105
Figure 126: Envelope requirement applied to a cylindrical feature	105
Figure 127: Envelope requirement applied to a cylindrical feature	106
Figure 128: Envelope requirement applied to a cylindrical feature	106
Figure 129: Envelope requirement applied to a cylindrical feature	106
Figure 130: Examples of maximum material condition	109
Figure 131: Positional tolerance for a group of holes, indication on the drawing	112
Figure 132: Positional tolerance for a group of holes, interpretation	112

Figure 133: Positional tolerance for a group of holes, indication on the drawing	113
Figure 134: Positional tolerance for a group of holes, interpretation	113
Figure 135: Four holes all being at their maximum material	114
Figure 136: Larger scale of Figure 135	114
Figure 137: Corresponding pins at their maximum material size	115
Figure 138: Enlarged detail of Figure 137	115
Figure 139: Hole at least material size	116
Figure 140: Pin at least material size	117
Figure 141: Perpendicularity tolerance of a shaft related to a datum plane	117
Figure 142: Figure 141 with the addition of $\textcircled{E}$ and $\textcircled{M}$	119
Figure 143: Straightness tolerance of an axis	120
Figure 144: Parallelism tolerance of a shaft related to a datum plane	121
Figure 145: Perpendicularity tolerance related to a datum plane	123
Figure 146: Angularity tolerance of a slot related to a datum plane	124
Figure 147: Positional tolerance of four holes related to each other	126
Figure 148: Dynamic tolerance diagram for Figure 147	127
Figure 149: Virtual condition for Figure 147	128
Figure 150: Figures 131 and 133 with zero geometrical tolerancing applied	128
Figure 151: Four holes related to each other	129
Figure 152: Dynamic tolerance diagram for Figure 151	130

Figure 153: Four pins relating to each other	131
Figure 154: Dynamic tolerance diagram for Figure 153	131
Figure 155: Virtual condition for Figure 153	132
Figure 156: Positional tolerance of four holes related to a datum hole	133
Figure 157: Virtual condition of Figure 156	135
Figure 158: Coaxiality tolerance	136
Figure 159: Virtual condition of Figure 158	138
Figure 160: Illustration of the least material requirement	139
Figure 161: Least material requirement, minimum wall thickness	140
Figure 162: Least material requirement, maximum face distance	141
Figure 163: Least material requirement, minimum wall thickness	142
Figure 164: Least material requirement, minimum wall thickness with perfect form at least material condition (LMC)	143
Figure 165: Basic graphical symbol to indicate surface texture	147
Figure 166: Graphical symbol to indicate removal of material by machining	147
Figure 167: Graphical symbol to indicate no removal of material	148
Figure 168: Graphical symbol to indicate special surface texture characteristics	148
Figure 169: Graphical symbol to indicate the same surface texture is required on all surfaces around workpiece	148
Figure 170: Indications of surface texture relative to the graphical symbol	149

Figure 171: Surface texture parameter value added to basic graphical symbol	150
Figure 172: Surface texture parameter value added to symbol for removal of material by machining	150
Figure 173: Surface texture parameter value added to symbol for no material to be removed	150
Figure 174: Upper and lower surface texture parameter values added to basic graphical symbol	150
Figure 175: Method of surface texture indicated in words on graphical symbol	151
Figure 176: Treatment or coatings to surface texture on graphical symbol	151
Figure 177: Indication of sampling length on graphical symbol	152
Figure 178: Indication of surface lay by working on graphical symbol	152
Figure 179: Orientation of graphical symbols in relation to drawings	154
Figure 180: Graphical symbol connected to the surface by a leader line	154
Figure 181: Surface roughness requirement indicated in connection with dimension	155
Figure 182: Graphical symbol used only once for a given surface	155
Figure 183: Separate indication of each prismatic surface	155
Figure 184: Indication of the same surfaces texture on the majority of surfaces of a part	156
Figure 185: Indication of the same surface texture on the majority of surfaces of a part	156
Figure 186: Simplified indication of surface texture	156

Figure 187: Basic graphical symbol, given with meaning	157
Figure 188: Symbol to indicate removal of material by machining, given with meaning	157
Figure 189: Symbol to indicate no removal of material, given with meaning	157
Figure 190: Graduated scale for microcopying	165
Figure 191: Example mechanical engineering drawing: swivel bracket	170
Figure 192: Example mechanical engineering drawing: connector	171
Figure 193: The link between design intent and metrology	238
Figure 194: Implementation plan	242
Figure 195: The GPS matrix model	243